



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ

ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।

Phone/Fax No. 0161-2420082

Email-ID :- eepdldnpwdpb@gmail.com

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ
ਬੀ.ਸੀ.ਐਮ. ਸੀਨੀ. ਸੈਕ. ਸਕੂਲ,
ਬਸੰਤ ਸਿਟੀ ਪੱਖੋਵਾਲ ਰੋਡ,
ਲੁਧਿਆਣਾ।

ਨੰ. 2349

ਮਿਤੀ: 1. 8. 2025

ਵਿਸ਼ਾ:- Regarding issue of Building Safety Certificate.

ਹਵਾਲਾ: ਆਪ ਦਾ ਪੱਤਰ ਨੰ.-BCM/BC/2024-25/8889 ਮਿਤੀ 28/03/2025.

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਤੇ ਹਵਾਲੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਬੀ.ਸੀ.ਐਮ. ਸੀਨੀ. ਸੈਕ. ਸਕੂਲ ਬਸੰਤ ਸਿਟੀ ਪੱਖੋਵਾਲ ਰੋਡ, ਲੁਧਿਆਣਾ ਦਾ ਨਿਰੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੁਧਿਆਣਾ ਵੱਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਉਨ੍ਹਾਂ ਦੀ ਰਿਪੋਰਟ ਮੁਤਾਬਕ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਮਿਤੀ 31/03/2026 ਤੱਕ ਸਹੀ ਜਾਪਦੀ ਹੈ। ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਵਿੱਚ ਇਸ ਦਫਤਰ ਦੀ ਮਨਜ਼ੂਰੀ ਤੋਂ ਬਗੈਰ ਕੋਈ ਵੀ ਐਡੀਸ਼ਨਲ ਅਲਟਰੇਸ਼ਨ ਨਾ ਕੀਤੀ ਜਾਵੇ।

ਨੱਥੀ/ਸਰਟੀਫਿਕੇਟ

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੁਧਿਆਣਾ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪੱਤਰ ਨੰ. 385 ਮਿਤੀ 28/07/2025 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਅਤੇ ਅਗਲੀ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।



Part-II
(To be filled by S.D.E. of P.W.D. B&R Department)

I have visited the above mentioned school on 25/7/25 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.


In case the building is affected by flood or if there is settlement of walls / foundations or caves of roof etc immediately inspection of the undersigned be arranged to check the stability and safety of the building.

The Area as written in the application form has been verified and found correct as per site.

The fee submitted is correct as per built up area of School and Govt. notification for fees.

The fee deposited by the School has been verified on portal.

This building can be safely occupied for normal use up to 31/3/26 (indicate year up to which it can be used).


Sub Divisional Engineer
Provincial Division No. 3,
P. W. D. B & R Br., Ludhiana.